
From PS Magazine Pg. 48:



Some guys didn't realize this when they read Step 4, page 51, in TM 9-2320-211-10. So the hydraulic pump didn't run fast enough to open the vanes all the way. The vanes got to chattering, and pretty soon the pump went bust.

Now there's no mistaking what the TM means, because, in Ch 2 (Jun 64), it says: "Pull throttle control valve to full open position."